

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERTL. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE Lieutenant Governor

Representa

presentativ	es Present During the Inspection:	
Company	Scott Dimick Superintendent	
OGM	Pete Hess Environmental Scientist III	

# **Inspection Report**

Permit Number:	C0070033
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, August 17, 2004
Start Date/Time:	8/17/2004 1:00:00 PM
End Date/Time:	8/17/2004 1:50:00 PM
Last Inspection:	Thursday, July 22, 2004

Inspector: Pete Hess, Environmental Scientist III

Weather: Overcast; raining. 70's F. InspectionID Report Number: 370

Accepted by: whedberg

9/22/2004

Permitee: ANDALEX RESOURCES INC TOWER DIVISION Operator: ANDALEX RESOURCES INC TOWER DIVISION

Site: WILDCAT LOADOUT

Address: PO BOX 902, PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Cu	rren	4	۸.	ra	24	00
Cu:	rren	L	ИC	re	aa	es

100.00	<b>Total Permitted</b>
63.70	<b>Total Disturbed</b>
	Phase I
	Phase II
	Phase III

#### **Types of Operations Mineral Ownership**

✓ Federal	Underground
☐ State	Surface
☐ County	✓ Loadout
Fee	Processing
Other	Poprocesing

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

Inspector's Signature

Pete Hess, Environmental Scientist III Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov



**Date** 

Tuesday, August 17, 2004

Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Tuesday, August 17, 2004

Page 2 of 3

### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  For PARTIAL inspections check only the elements evaluated.
- Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
  Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
  Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V			
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<b>V</b>			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	Roads: Construction, Maintenance, Surfacing	✓		<b>~</b>	
16.	Roads: Drainage Controls	✓		<b>V</b>	
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

**Inspection Continuation Sheet** 

Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Tuesday, August 17, 2004

Page 3 of 3

# 16.a Roads: Construction, Maintenance, Surfacing

During the week following the July 22, 2004 inspection, the permiittee made two applications of magnesium chloride to the roadway surfaces of the following primary roads located in the disturbed area: 1) PR-3, and the pad area adjacent to the scale house to the junction of PR-2, (See PLATE 1, Wildcat MRP), 2) PR-2, which is the unpaved portion of road PR-1 (East side truck access gate), to the junction with PR-3. 3) PR-6, which parallels the railroad tracks from the electrical substation to the rail loading facility; 4) PR-10, which is the east loop at the rail loadout, returning to PR-6. The first application of chemical was made on or about July 26th, with the second application being made three days later. The road surfaces were flat and did not contain "chuck holes". The Carbon County area has received several rainfall events over the past week, with the most recent occurring overnight. As noted above, it was also raining during today's inspection.

## 16.b Roads: Drainage Controls

Several ditches were noted as having weed growth within them.